

1998 Annual Report Review

Permittee: Hiawatha Coal CompanyMine Name: Hiawatha ComplexPermit Number: ACT/007/011Date Report Received April 7, 1999Assigned Reviewers: Paul Baker, Pete Hess, Dave Darby

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine folder #6.

Assignments: Inspectors: Review cover sheet, AVS legal/financial, Mine sequence map

Hydrologists: Review water monitoring data, Precipitation and climatological data, Non-coal waste

Biologists: Review vegetation/revegetation success monitoring, Raptor survey

Engineers: Review subsidence monitoring data, Annual impoundment certification, Annual overburden, spoils, refuse, floor, etc.

Section to review	Submitted Yes	No	Findings
Cover sheet	<u>X</u>	—	
AVS; Legal/Financial Update	<u>X</u>	—	
Mine Sequence Map	—	<u>X</u>	There has been no mining except from the slurry ponds in the past few years. The report includes information about fines recovery.
Water Monitoring Data	<u>X</u>	—	Submitted according to monitoring plan
Precipitation & Climatological Data	<u>X</u>	—	Submitted in MRP
Non-Coal Waste report	<u>X</u>	—	Addressed in MRP
Subsidence monitoring data	<u>X</u>	—	P.E. Certified by Charles Reynolds. 112 monitoring points are checked. Maximum deflection = -1.46' at point 409

Annual Impoundment Certification	<u>X</u> —	all poind certifications P.E. verified. No hazards noted/ ponds 003, 004, 006, 007 need cleaning in spring of 99.
Annual Overburden, Spoil, Refuse, Floor, etc.	<u>X</u> —	Refuse pile #1 inactive. No fires, hazards or signs of instability reported. P.E. cerigation OK.
Vegetation data	— <u>X</u>	No information required.
Revegetation Success monitoring	— <u>X</u>	No information required.
Raptor survey	— <u>X</u>	No information required.
Other information	<u>X</u> —	Submitted sedimentation and slurry pond certification.

O:\007011.HIA\ANNUALRPI\REVIEW.FRM

007611 #6

1998 Annual Report Review

Permittee: Hiawatha Coal Company, Inc.
 Mine Name: Hiawatha Complex
 Permit Number: ACT/0074011
 Date Report Received: 4/7/99 SLO / 4/12/99 PFD-DDGM

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the Mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, a copy will be filed in the Mine folder #6.

Assigned Reviewers: Peter Hess, Engineer

Section to review	Submitted	Yes	No	Findings
Cover sheet		—	—	
AVS; Legal/Financial Update		—	—	
Mine Sequence Map		—	—	
Water Monitoring Data		—	—	
Precipitation & Climatological Data		—	—	
Non-Coal Waste		—	—	
* Subsidence monitoring data		*	—	P.E. certified by Charles Reynolds 112 monitoring points are checked Maximum deflection = -1.46' at point 409
* Annual Impoundment Certification		*	—	All pond certifications P.E. verified. No hazards noted/Ponds 003, 004, 006, 007 need cleaning in Spring of '99.
* Annual Overburden, Spoil, Refuse, Floor, etc.		*	—	Refuse pile #1 inactive No fires, hazards, or signs of instability reported. P.E. certification OK.
Vegetation data		—	—	
Revegetation Success monitoring		—	—	

Hiawatha Coal Company

P.O. Box 1202
Huntington, UT 84528

(435) 637-1778
FAX (435) 637-1378

March 29, 1999

Coal Program
Utah Division of Oil, Gas & Mining
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

ACT/007/011 #6


To Whom It May Concern,

Re: Annual Report, 1998, Hiawatha Coal Company, Hiawatha Complex,
ACT/007/011, Carbon County, Utah

Enclosed is the Annual Report for 1998 for the Hiawatha Complex

If you have any questions, please call me at (435) 637-1778.

Sincerely,


Elliot Finley
President

CR

